



Bearing Installation

- Mating components such as shafts and housings must be designed with proper surface geometry and fits for bearing mounting.
- Mating components and assembly tooling must be clean, free of burrs, and demagnetized.
- Tooling should be designed to mount the bearings squarely onto the shaft and into the housing. Any misalignment during installation can severely distort a bearing.