

# Preload

## ■ Advantages

- Remove Radial and Axial Play
- Reduce Noise Improve Shaft Positioning
- Maintain Ball/Race Contact to Reduce Skidding and Vibration
- Increase Stiffness

## ■ Disadvantages

- Increase Heat
- Increase Torque

